

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM		Page 1 of 4
Sewershed: Low Level Subsewershed: 42	Company: REI/DRAYCO	Date: 09/11/2008
Test Type: Smoke	Ground Condition: Dry: <input checked="" type="checkbox"/> Damp: <input type="checkbox"/> Wet: <input type="checkbox"/>	Supervisor: E.R. Crew: 04
Manhole ID: S21W__037MH	Test ID: 1029-547	Notifications Made: <input type="checkbox"/> X___ Residents, Fire, 311
Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)		
<p>The field sketch is a map of a residential area with streets and building footprints. A red line traces a path through several manholes, labeled with numbers: 029, 026, 012, 018, 023, 001, 002, and 037. A yellow line is also visible in the upper left. A blower is indicated at manhole 037. Labels with red boxes and arrows point to specific locations: '547_OB01-01' points to a location near manhole 002, 'BLOWER #1 S21W__037MH' points to manhole 037, and '547_OB02-01' points to manhole 023. Street names and building addresses are visible on the map, including 2331, 2000, 1907, 1909, 1911, 1913, 1915, 1917, 1919, 1922, 1923, 1924, 1925, 1926, 1927, 1928, 1929, 1930, 1931, 1932, 1933, 1934, 1935, 1936, 1937, 1938, 1939, 1940, 1941, 1942, 1943, 1944, 1945, 1946, 1947, 1948, 1949, 1950, 1951, 1952, 1953, 1954, 1955, 1956, 1957, 1958, 1959, 1960, 1961, 1962, 1963, 1964, 1965, 1966, 1967, 1968, 1969, 1970, 1971, 1972, 1973, 1974, 1975, 1976, 1977, 1978, 1979, 1980, 1981, 1982, 1983, 1984, 1985, 1986, 1987, 1988, 1989, 1990, 1991, 1992, 1993, 1994, 1995, 1996, 1997, 1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100.</p>		

[illegible]

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 547	Date: 09/11/2008	Basin: LL - 42	Manhole ID: S21W__037MH
Defect No: OB01	Supervisor: E.R.	Crew: 04	Dye Test Recommended: N
Location: S21W__002MH			
Source Type: 18 Other		Location: 09 Yard - Side	
Sector: 02 Private		Severity: 03 Moderate	Drainage Area: 50
Comments: THIS IS SUSPECTED LOCATION OF MANHOLE S21W__002MH. SMOKE IS COMING FROM LARGE AREA AND SUSPECT THERE MAY BE AN UNKNOWN DEFECT.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01
Filename: 1029-547_OB01-01.jpg

CITY OF BALTIMORE
SMOKE TESTING OBSERVATION SUMMARY
LOW LEVEL SEWERSHED
BALTIMORE CITY PROJECT 1029
REI/DRAYCO

Unique Test ID: 547	Date: 09/11/2008	Basin: LL - 42	Manhole ID: S21W__037MH
Defect No: OB02	Supervisor: E.R.	Crew: 03	Dye Test Recommended: N
Location: 1921 BREITWERT AVE.			
Source Type: 12 Catch Basin		Location: 06 Curb	
Sector: 01 Public		Severity: 03 Moderate	Drainage Area: 2000
Comments: SMOKE IS COMING FROM THIS CATCH BASIN. NOTE - BALTIMORE CITY CREWS WERE WORKING ON A GAS LINE HERE.			

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01
Filename: 1029-547_OB02-01.jpg